



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Green River District, Price Field Office

125 South 600 West

Price, UT 84501

<http://www.blm.gov/ut/st/en/fo/price.html>



FEB 09 2015

IN REPLY REFER TO:

3809

(GO2100)

UTU- 87376

S/015/0077

RECEIVED

FEB 13 2015

DIV. OF OIL, GAS & MINING

Wayne Western
Utah Division of Oil, Gas, and Mining
1594 West North Temple, Suite 1210
P. O. Box 145801
Salt Lake City, Utah 84114-5801

RE: Bond Release for Goldterra's Blue Castle Mine; T16S, R14E, Sec 29; S/015/0077

Dear Mr. Western:

A site inspection and file review was conducted on January 19, 2015 for the Goldterra Blue Castle Mine located at T16S, R14E, Section 9, Emery County, Utah. The inspection revealed that the land disturbance associated with the exploration activity has been adequately reclaimed. The majority of the disturbance area was situated on barren Mancos Shale Formation badlands topography and does not require reseeding. The approximately 10-foot wide and 1,000 -foot long access road was also reclaimed; it was sufficiently roughed up to encourage re-vegetation from locally derived seeds. The Price Bureau of Land Management recommends that the entire bond (\$12,000) be refunded to Goldterra as reclamation is now considered complete. This action officially closes project UTU-87376, also known as: S/015/0077.

If you have any questions or comments please contact Chris Conrad at (435) 636-3612.

Sincerely,

Ahmed Mohsen
Field Manager

CC: Opie Abeyta: BLMSO